


## "DANGER!" - Electrical Shock Hazard





Internal Wiring = COAX Cable (apx. 0.7 ft)



Eco 15774; Updated Connector Description. Rotated Tool Side View 180°. Updated Electrical Shock Note. Updated Notes.

Internal Wiring: Single COAX Cable.
Connector Shield Tied to Chassis Ground.

60.2



1031 Goodworth Drive, Apex, NC 27539, USA Tel: +1.919.772.0115 Email: info@ati-ia.com Fax: +1.919.772.8259 www.ati-ia.com ISO 9001 Registered Company

PROPERTY OF ATI INDUSTRIAL AUTOMATION, INC. NOT TO BE REPRODUCED IN ANY MANNER EXCEPT ON ORDER OR WITH PRIOR WRITTEN AUTHORIZATION OF ATI.



3rd ANGLE PROJECTION

CHECKED BY: A. Strotzer, 6/20/07

DRAWN BY: D.Lawson, 6/19/07

75 Ohm Ultrasonic Coax Module

SCALE

DRAWING NUMBER

PROJECT # 070202-1 SHEET 1 OF 1 1:1 В 9630-20-X7C 03

REVISION

DATE

SHV/Coaxial Connector,

6/13/2017